

Garrane Green Energy Project, Charleville, Co. Limerick

Supplementary Site Investigation Works for Construction of New Wind Turbines, Access Tracks and Associated Infrastructure

Report No: 2177-22C

7th September 2024

This document has been prepared by Whiteford Geoservices Ltd on behalf of

Garrane Green Energy Ltd &
Jennings O'Donovan Ltd









CONTENTS

1	INTR	ODUCTION	1
2	SITE 2.1 2.2		4
3	3.1 3.2	Exploratory Holes In-situ Testing	7
4	LAB (4.1	ORATORY TESTING Geotechnical Testing	10
5	SUR \ 5.1 5.2		11
5	REFE	ERENCES	15

APPENDICES

- A DRAWINGS
- B PEAT DEPTHS ENCOUNTERED AT WIND TURBINE GENERATOR BASES ENGINEERING LOGS OF TRIAL HOLES
- C INTERPRETED GEOPHYSICAL SURVEY DATA
- D SOILS LABORATORY TESTING
- E PHOTGRAPHIC RECORD



1 INTRODUCTION

This report should be read in conjunction with the following two reports: -

- Garrane Green Energy Project "Desktop Study and Walkover Survey for Preliminary Determination of Ground Conditions", Report 2177-22A.
- 2. Garrane Green Energy Project, Charleville, Co. Limerick, "Preliminary Site Investigation Works for Construction of New Wind Turbines, Access Tracks and Associated Infrastructure", Report 2177-22B.

In July 2022 Whiteford Geoservices Ltd was commissioned by Jennings O'Donovan Ltd to undertake investigation works at Garrane Green Energy Project near Charleville, County Cork, Ireland.

A total of two phases of ground investigation were carried out, as follows: -

- 1. Stage 1 Site investigation works carried out for the turbines and associated infrastructure for the 12-turbine development, named "Garrane Green Energy Project".
- 2. Stage 2 Supplementary site investigation works carried out for turbines, substation and associated infrastructure relating to the updated 9 turbine development, renamed as "Garrane Wind Farm".

These investigations were required to obtain information for the civil design of access tracks and other infrastructure; primarily with respect to the assessment of soils and geology in relation to an application for planning permission in respect to: -

A total of 9nr new wind turbine generators, associated infrastructure and turbine hardstands as well as new and upgraded site access tracks and construction of a new Substation.

Prior to undertaking the site investigation works a desktop study and walkover survey had been undertaken for the site to provide a broad understanding of ground conditions present and an initial assessment of peat stability. As part of the desktop study and walkover report preliminary Peat Depth and Ground Slope plots were compiled and from this and other observations a Preliminary Plot of Peat Slide Risk Hazard had been compiled.

The results of this stage 1 site investigation were then employed to screen for the significance of peat soil thickness in respect to peat landslide susceptibility. The



same information was also analysed to gain a clearer understanding of the nature of soils and rock present along the proposed route of the access track network, at the proposed wind turbine generators, hardstandings and other infrastructure to be constructed as part of the wind farm development.

This analysis determined that peat is not present in sufficient depth, at the Site, to cause peat landslide. Peat soils were not identified within the wind farm boundary.

Stage 2 supplementary site investigation works for undertaken following a change to the proposed wind farm layout to the 9-turbine arrangement for Garrane Green Energy Project.

The scope of these 2 phases of site investigation works was as follows: -

Ref	SI Component	Remarks
STAGE 1 SITE IN	IVESTIGATION	
A	Peat probing	In-situ assessment of peat thickness at wind turbine generators (12nr)
В	Trial pitting to determine the underlying soil type, its thickness overlying rock and the relative competence of each stratum.	A total of 6nr Trial pit exploratory holes to assess ground conditions.
С	Laboratory testing of soils	To determine preliminary geotechnical parameters for foundation design
STAGE 2 SITE IN	VESTIGATION	
A	Peat probing	In-situ assessment of peat thickness at wind turbine generators
В	Trial pitting to determine the underlying soil type, its thickness overlying rock and the relative competence of each stratum.	A total of 4nr Trial pit exploratory holes to assess ground conditions at the Substation.
С	Geophysical Profiles at the locations of T1, T2, T3, T4, T5, T6, T7, T8, T9 and the Met Mast	2nr approximately orthogonal 2D ERT profiles were undertaken to assess ground conditions at the main infrastructure.
D	Laboratory testing of soils	To determine preliminary geotechnical parameters for foundation design

Table 1 – Scope of SI Works



The investigation was performed in accordance with the relevant standards (see References) and data presented within the relevant appendix to this report.

This report presents the factual records of the investigations undertaken.



2 SITE AND GEOLOGY

2.1 The Site

Garrane Green Energy Project is situated approximately 1km north of Charleville,

County Cork and straddles relatively flat lands that slope generally in a northerly

direction.

Ground surface elevations vary between approximately 59m to 67m above Ordnance

Datum (Malin Head).

The land usage does not appear to vary across the number of land holdings which

make up the Garrane Green Energy Project, consisting of agricultural pastureland for

grazing sheep and cattle.

The closest active quarrying operations to the site are set out in Appendix 9.1,

Section 2.7, the closest is approximately 7km to the south.

2.2 Published Geology

A study was made of available geological information for the area (GSI Online

Database). This study indicated that the following natural geology is present across

the site of Garrane Green Energy Project;

Lacustrine deposits

Boulder Clay

River Deposits

• Limestone rock

2.2.1 Solid Geology

According to the GSI online database, the Site is underlain by a succession of

Limestone formations. Those being the Visean Limestones, Ballysteen Formation

and the Waulsortian Limestones

Visean Limestones; undifferentiated limestones

Ballysteen Formation; dark muddy limestone interbedded with shale

Waulsortian Limestones; undifferentiated limestones

whiteford

Whiteford Geoservices Ltd Straid House, BALLYCLARE, UK BT39 9NE Registration No: NI44990 The rock formations are also bisected by a series of faults that trend both in a south west – north east direction and in a west to east direction. These indicate previous differential movement between adjacent rock formations the date of which is unknown.

Two of which faults cut directly across the wind farm site. It is unlikely that these faults will be re-activated during the lifetime of the wind farm; Ireland being one of the less seismically active parts of the world. However, it is probable that these fault zones will be associated with highly fractured and locally weaker rock masses. Such conditions can have significance for foundation design of structures such as wind turbines and warrant further investigation at construction phase.




Figure 1 – Bedrock Solid Geology Reproduced courtesy of GSI Datasets Public Viewer

2.2.2 Superficial Geology

Superficial soils present within the wind farm boundary largely consists of lake (lacustrine) deposits and river deposits (alluvium). The northern and southern



extents of the site are underlain by glacial till, with small pockets of gravels present elsewhere.




Figure 2 – Superficial Geology Reproduced courtesy of GSI Datasets Public Viewer

For further information pertaining to site geology refer to the Desk Study and Walkover Survey Report (2177-22A).

3 FIELDWORK

3.1 General

All fieldwork was carried out in general accordance with BS 5930:2015+A1:2020 and other related standards.

Please refer to Appendix A for the location of all geotechnical investigations undertaken.

3.2 Exploratory Holes

The exploratory holes are detailed within the following table.

METHOD	QUANTITY	MAXIMUM DEPTH (m)	EQUIPMENT
Trial Pit	6 Nr.	3.60	Trial pits were carried out with the use of a 13T Tracked Excavator

Table 2A - Stage 1 Trial Hole Works

METHOD	QUANTITY	MAXIMUM DEPTH (m)	EQUIPMENT
Trial Pit	4 Nr.	3.80	Trial pits were carried out with the use of a 13T Tracked Excavator

Table 2B – Stage 2 Trial Hole Works

Refer to Appendix B for engineering logs of trial holes

3.3 In-situ Testing

The in-situ testing works carried out are detailed within the following table.

STAGE 1

TYPE	QUANTITY	MAX. DEPTH (M)	EQUIPMENT
Peat Probing	12 ¹	0.00	Rigid "depthing rods"

Table 3 – Stage 1 Peat Probing

¹ Additional peat probes were undertaken during this phase of the works at turbines and hardstands. Previously 106 peat probes had been undertaken during the Walkover phase of the assessment.



Refer to Appendix B for details

3.4 Geophysical Surveys

The geophysical survey involved the following non-destructive testing techniques.

METHOD	LOCATION	MAXIMUM DEPTH (m)	EQUIPMENT
2D Electrical Resistivity Tomography	2 Nr. Orthogonal profiles at "wind turbine generators T1, T2, T3, T4, T5, T6, T7, T8, T9 and the Met Mast	approx. 15m	Campus Tigre Electrical Resistivity Imaging System.

Table 4 - GPR and Geophysical Methods Deployed

2D Electrical Resistivity

A Campus Tigre Electrical Resistivity System employing a 32 electrode Wenner Array was used to conduct the geophysical 2D resistivity survey, with the intention of analysing the sub-surface to a depth of approximately 15m below existing ground level.

Field quality-controlled data processing was carried out using Imager Pro 2006.

Two electrodes input a controlled electrical current into the ground, where the lines of current flow adapt to the sub-surface resistivity pattern. In this way the potential difference between the equipotential surfaces can be measured, where they meet the ground surface, using a second pair of electrodes. Comparison of the input current to the measured potential difference enables the resistance to be calculated.

Imager Pro 2006, a Windows acquisition program allows real time colour pseudosections to be generated on the laptop computer used to collect and store data in the field. Such real time presentation offers instant confirmation of data quality.

Res2DinV software was applied to the field data to provide the modelled sections which were then interpreted, in terms of resistivity, by an experienced Geologist.

Refer to Appendix C for the annotated 2D Electrical Resistivity profiles collected.



3.5 Topographical Survey

A topographical survey of exploratory hole locations was undertaken post-completion of all associated investigation works and is detailed in the table below.

EQUIPMENT	COORDINATE SYSTEM
Leica RTK / GNSS DGPS System	Irish Transverse Mercator (ITM) / Malin Hean (Ordnance Datum)

Table 5 – Topographic Survey Details



4 LABORATORY TESTING

4.1 Geotechnical Testing

Following detailed analysis soils laboratory testing was undertaken on stage 1 samples collected from the site.

This testing was scheduled and carried out in accordance with BS 1377 (1990) and BS 1377 Part 3 (2018) other standards by Whiteford Geoservices Ltd.

A schedule of this testing is summarised in the table below and the results are presented within Appendix D.

ТҮРЕ	QUANTITY	REMARKS
Atterberg Limits	4	BS1377:1990 Part 2 (1990)
Bulk Density	10	BS1377:1990 Part 2 (1990)
Dry Density	6	BS1377:1990 Part 2 (1990)
Natural Moisture Content	4	BS1377:1990 Part 2 (1990)
Partial Size Distribution	10	BS1377:1990 Part 2 (1990)
Sulphate Content of Water Extract	10	BS 1377- Part 3 (2018)
Chloride Content of Water Extract	10	BS 1377- Part 3 (2018)
Sulphide Content of Water Extract	10	BS 1377- Part 3 (2018)
рН	10	BS 1377- Part 3 (2018)

Table 6 - Laboratory Soil Test Details



5 SURVEY RESULTS

5.1 Introduction

The investigation has provided geophysical information on the sub-surface conditions within the zones identified on the Geophysical Layout Plans in Appendix A.

Refer to Appendix C for annotated findings for the 2D Electrical Resistivity Surveys.

5.2 Soil Stratigraphy at Turbines

The following Table details the findings of preliminary exploratory holes undertaken at proposed Wind Turbine positions. Refer to Appendix B for individual engineering logs of exploratory holes and Appendix C for interpreted geophysical survey findings.

TURBINE NO.	TOPSOIL THICKNESS / DEPTH TO FIRM MINERAL SOILS (M)	SUITABLE FORMATION DEPTH FOR TRACKS AND HARDSTANDS DEPTH TO FIRM MINERAL SOIL (M)	SUMMARY OF FINDINGS – GEOPHYSICAL SURVEYS
Т1	0.15 - 0.45	0.45 – 0.75	4m – 5m of low resistivity soils (probably clays or sands) overlying deeply weathered or fractured limestone rock. Limestone generally competent below 6m depth.
Т2	0.15 – 0.45	0.45 – 0.75	4m – 6m of low resistivity soils (probably clays or sands) overlying deeply weathered or fractured limestone rock. No competent limestone identified. Potentially "karstic"
Т3	0.15 – 0.45	0.45 – 0.75	4m – 5m of low resistivity soils (probably clays or sands) overlying very low resistivity, degraded, limestone rock. Potentially "karstic"
Т4	0.15 – 0.45	0.45 – 0.75	3.5m - 4.5m of low resistivity soils (probably clays or sands) overlying deeply weathered or fractured limestone rock. Competence of limestone is variable across profiles. Potentially "karstic"



TURBINE NO.	TOPSOIL THICKNESS / DEPTH TO FIRM MINERAL SOILS (M)	SUITABLE FORMATION DEPTH FOR TRACKS AND HARDSTANDS DEPTH TO FIRM MINERAL SOIL (M)	SUMMARY OF FINDINGS – GEOPHYSICAL SURVEYS
T5	0.15 – 0.45	0.45 – 0.75	4m – 5m of low resistivity soils (probably clays or sands) overlying deeply weathered or fractured limestone rock. Limestone generally competent below 5m depth.
Т6	0.15 – 0.45	0.45 – 0.75	c. 4m of low resistivity soils (probably clays or sands) overlying very low resistivity material. Either, degraded, "karstic" limestone rock or more competent mineral soils.
Т7	0.15 – 0.45	0.45 – 0.75	c. 4m of low resistivity soils (probably clays or sands) overlying very low resistivity material. Either, degraded, "karstic" limestone rock or more competent mineral soils.
Т8	0.15 – 0.45	0.45 – 0.75	3.5 – 4.5m of low resistivity soils (probably clays or sands) overlying very low resistivity material. Either, degraded, "karstic" limestone rock or more competent mineral soils.
Т9	0.15 – 0.45	0.45 – 0.75	c. 4m of low resistivity soils (probably clays or sands) overlying very low resistivity material. Either, degraded, "karstic" limestone rock or more competent mineral soils.
Met Mast	0.15 – 0.45	0.45 – 0.75	2 – 3m of low resistivity soils (probably clays or sands) overlying generally competent limestone rock.
Substation	0.10 – 0.20	1.60	N/A
Substation Compound	0.20	1.20 – 1.40 (Soft to firm). Alternating sequence of soft to firm and stiff mineral soils.	N/A

Table 7 – Summary of Stratigraphy at Main Infrastructure

In light of the findings from the preliminary trial hole works the following schedule of foundations is recommended for the main infrastructure



TURBINE NO.	TURBINE / BUILDING	HARDSTAND / TRANSFORMER BASE / COMPOUND	ACCESS TRACKS
T1	Gravity Base Foundation possible within stiff or loose to medium dense mineral soils	Place at 0.45m to 0.75m depth within firm mineral soils	
T2	Gravity Base Foundation possible within stiff or loose to medium dense mineral soils	Place at 0.45m to 0.75m depth within firm mineral soils	
Т3	Gravity Base Foundation possible within stiff or loose to medium dense mineral soils	Place at 0.45m to 0.75m depth within firm mineral soils	
T4	Within predicted flood zone. Deep Foundation recommended. Piled, rock anchored design or suitable alternative.	Place at 0.45m to 0.75m depth within firm mineral soils. Hardstand is within the predicted food zone. Upgraded design and / or enhanced maintenance will be required.	Remove all soft or very weak soils and commence road construction within firm CLAY/SILT or loose SAND
Т5	Within predicted flood zone. Deep Foundation recommended. Piled, rock anchored design or suitable alternative.	Place at 0.45m to 0.75m depth within firm mineral soils. Hardstand is within the predicted food zone. Upgraded design and / or enhanced maintenance will be required.	mineral soils (0.45m - 0.75m depth). Tracks to be constructed within the predicted flood zone will require upgraded design and / or enhanced maintenance during
Т6	Within predicted flood zone. Deep Foundation recommended. Piled, rock anchored design or suitable alternative.	Place at 0.45m to 0.75m depth within firm mineral soils. Hardstand is within the predicted food zone. Upgraded design and / or enhanced maintenance will be required.	the Development's lifetime.
T7	Within predicted flood zone. Deep Foundation recommended. Piled, rock anchored design or suitable alternative.	Place at 0.45m to 0.75m depth within firm mineral soils. Hardstand is within the predicted food zone. Upgraded design and / or enhanced maintenance will be required.	



TURBINE NO.	TURBINE / BUILDING	HARDSTAND / TRANSFORMER BASE / COMPOUND	ACCESS TRACKS
Т8	Within predicted flood zone. Deep Foundation recommended. Piled, rock anchored design or suitable alternative.	Place at 0.45m to 0.75m depth within firm mineral soils. Hardstand is within the predicted food zone. Upgraded design and / or enhanced maintenance will be required.	
Т9	Gravity Base Foundation possible within stiff or loose to medium dense mineral soils	Place at 0.45m to 0.75m depth within firm mineral soils	
MET MAST	Raft Foundation within firm mineral soils	Place at 0.45m to 0.75m depth within firm mineral soils	
SUB	1.2m Strip / Pad or Raft Footing for Building on firm mineral soils at 1.60m depth. Allowable bearing pressure of 150kPa for max. 50mm settlement.	0.70 m depth within firm mineral soils. Given the variation in soil competence with depth we recommend an engineered base consisting of crushed rock / gravel and geotextile be designed to accommodate the proposed loads.	

Table 8 – Recommendations for Infrastructure Foundations

6 REFERENCES

BS 1377: 1990: Methods of test for soils for civil engineering purposes. British Standards Institution.

BS 5930:2015 + A1:2020 Code of practice for ground investigations. British Standards Institution.

BS EN 1997-2: 2007: Eurocode 7 - Geotechnical design - Part 2 Ground investigation and testing. British Standards Institution.

BS EN ISO 14688-1: 2002: Geotechnical investigation and testing - Identification and classification of soil - Part 1 Identification and description. British Standards Institution.

BS EN ISO 14689-1: 2003: Geotechnical investigation and testing - Identification and classification of rock - Part 1 Identification and description. British Standards Institution.

BS EN ISO 22475-1: 2006: Geotechnical investigation and testing – Sampling methods and groundwater measurements - Part 1 Technical principles for execution. British Standards Institution.

BS EN ISO 22476-2: 2005: Geotechnical investigation and testing - Field testing - Part 2 Dynamic probing. British Standards Institution.

BS EN ISO 22476-3: 2005: Geotechnical investigation and testing - Field testing - Part 3 Standard penetration test. British Standards Institution.

ISRM: 2007: The Complete ISRM Suggested Methods for Rock Characterisation, Testing and Monitoring (1974-2006). Commission on Testing Methods, International Society for Rock Mechanics (Editors Ulusay R & Hudson JA).

ASTM D5731-08: Standard test method for determination of the point load strength index of rock and application to rock strength



APPENDICES

Appendix A Drawings

Appendix B Exploratory Holes and In-situ Test Results

Appendix C Interpreted Geophysical Survey Data

Appendix D Laboratory Testing Results Employed for Analysis

Purposes

Appendix E Photographic Record



APPENDIX A DRAWINGS

General Site Location Plan	1 x A4
Site Layout Plan showing position of Exploratory Holes and Insitu	1 x A3
Tests	





P1 - General Location Plan (Aerial view) (© google maps 2021)



P2 - Local Location Plan (Aerial view) (© google maps 2021)



2177-22 Garrane Green Energy Project

Site Layout Plan - Garrane Green Energy Project Updated with SI Exploratory Works

Includes:

Notes:

All depths are relative to ground level existing at the time of the survey / investigation.
 All positions relate to the ITM coordinate system.
 Any elevations are provided relative to Ordnance Datum Malin Head

4. Do not scale from drawing: not to be used for measurement.5. Relates to Stage 2 SI Works undertaken between 17 July and 17 August 2024.

Trial Holes within Wind Farm Landholding Trial Holes at Substation and Battery Storage Site ERT Resistivity Profiles (all Turbines and Met Mast)



whiteford explore the possibilities

Garrane Green Energy Soils and Geology Assessment

Site Layout Plan - Phases 1 & 2 (SI Works - Sept 22 / Aug 24) Scale 1:7500


A3

Designed by J.W.

Whiteford Geoservices Ltd

Checked by

17th June 2025



APPENDIX B IN-SITU TEST RESULTS

Trial Pit Logs 10 x A4
Peat Probing Data 1 x A4



V	roject Name: Garrane green Energy Project- S.I. Project No. 2007 100 2007					Address: 2 Main Stre BT39 9NE, UK Tel: (028) 9334 9351 Email: Info@whitefor Website: www.whitef	dgeoservices	s.com		Tri	al P	it L	og	
Projec	t Name:	Garrane	3.1	Р	roject No:	Client: Garrane	Green E	nergy Ltd		Date: 19/08/202	24			
510011	Liloigy	i rojoot (J.1.		2177-22	Contractor: Wh	iteford Ge	eoservices	Ltd	Co-ords: E5551	28.39 N	625814	.67	
_ocati	on:					Sub Contractor	:			Equipment: Hita	achi ZAX	(IS 130L	CN	
Loc	TP-S0		L		on Type ГР	Level 63.75m A	oD		jed By OR	Scale 1:25			ge Numboneet 1 of	
Well	Water Strikes				Situ Testing Results	(m)	Level (m)	Legend		Stratum De	scription	1		
		0.50 1.00 2.70		Type B B B	Results	0.20	63.55 63.05 62.55		Stiff, brow silty CLAY Soft to firm gravelly S boulders. sub round Soft to firm silty, grave	nish mottled grey n, brownish mott OLT/CLAY, with: Gravel is fine to ed. n greyish brown, elly CLAY, with so Gravel is fine to	y, slightly led grey, some co coarse, slightly ome cob coarse,	y sandy, , sandy, ,bbles ar sub ang sandy, s	slightly nd gular to	2 -
														-
Dit	Dime Length	ensions Pit V	Vidth		Pit Stability	Shoring Used	Trench Co	mments	Remarke		Ton		Details Descrir	ntion
rit ;	5.00		80	5	Sides stable ough 1.40m to 3.80m	Shoring Osed			Remarks Top Base Description 0.00 3.80 Arisings					

Remarks

Groundwater seeping in at 3.00m



	V	white explore	fo the pos	rd	BT39 9f Tel: (02 Email: I	s: 2 Main Stree NE, UK 8) 9334 9351 Info@whiteford e: www.whitefo	dgeoservices	s.com		Tri	al P	Pit I	Log	
Project Green	t Name: Energy	Garrane Project- S.I.	Р	i Oject i vo.	Clien	t: Garrane	Green E	nergy Ltd		Date: 19/08/202	24			
				2177-22	Contr	ractor: Wh	iteford Ge	eoservices	Ltd	Co-ords: E5550	96.95 N	162593	4.38	
Locati					Sub (Contractor	: .			Equipment: Hita	nchi ZAX			
Loc	cation No TP-S0			on Type TP		Level 62.48m A	oD		jed By OR	Scale 1:25			age Nun Sheet 1 d	
Well	Water			Situ Testing		Depth	Level	Legend		Stratum De	scription			
**************************************	Strikes	Depth (m)	Туре	Results		(m)	(m)	Logona	TOPSOIL			•		
						0.20	62.28							
						0.20	02.20	× ×	Stiff, gree slightly gr	enish grey, slightly ravelly CLAY.	silty, sli	ightly s	andy,	
		0.50	В					XX						-
						0.60	61.88	XX-	Firm brow	vnish mottled grey	/ sandy	gravel	ly SILT/	- -
									CLAY, wit	h some cobbles a arse, sub angular	and boul	lders.	Gravel is	
										aroo, oaz arigaiar				-
								<u> </u>						1 -
		1.20	В											
						1.40	61.08	**************************************	Coff to fin		- I: I- 41		- I:I-41. ·	_ =
								<u> </u>	silty, grav	m greyish brown selly CLAY, with so	ome cob	bles a	nd	-
								<u> </u>	boulders. sub round	Gravel is fine to ded.	coarse,	sub ar	ngular to	-
								X - X - X - X						
														2 -
		2 20	В					× ×						-
		2.20	В					×=						
								X - X - X - X						-
														-
								<u> </u>						
								× × ×						-
								×						3 -
		3.20	В											-
								<u> </u>						
								× × ×						-
								×						-
)//////		3.80	В			3.80	58.68			End of Pit at	3.800m			+ :
														4 -
														-
														- - - -
														=
	Dime	ensions				7	French Co	omments				Backf	ill Details	
Pit (Pit Length Pit Width Pit Stability 5.00 1.80 Sides stable					ring Used			Remarks		Top 0.00	Base 3.80	Desc	cription sings
	through 1.40n 3.80m													-
Rema	arks													

No groundwater encountered. Wet soil from 1.40m

V	V	vhite explore	fo the poss	rc	Address: 2 Main Stre BT39 9NE, UK Tel: (028) 9334 9351 Email: Info@whitefor Website: www.whitef	dgeoservices	s.com		Tri	al F	Pit L	og	
Projec	t Name:	Garrane Project- S.I.	Р	roject No:	Client: Garrane	Green E	nergy Ltd		Date: 19/08/202	24			
51001	Liloigy	1 10,000 0.1.	:	2177-22	Contractor: Wh	iteford Ge	eoservices	Ltd	Co-ords: E5550	38.80 N	1625796.	30	
_ocati	on:				Sub Contractor	:			Equipment: Hita	ichi ZΑλ	(IS 130L	CN	
Lo	cation No			on Type	Level 62.63m A	۵۵		jed By	Scale			ge Numbe	
Well	TP-S0			TP Situ Testing	J Depth	Level		OR	1:25 Stratum De	scription	1	eet 1 of 1	
Well	Water Strikes	2.00 3.00 3.80	B B B	Results	(m)	Level (m) 62.43 62.13	Legend A TALL REPORT OF THE PROPERTY OF THE P	Firm to st sub rou	nish grey, silty, sli CLAY. iff brownish mottle Y. Gravel is fine sunded. Some cotton iff greyish brown, avelly CLAY, with Gravel is fine to	ghtly sa ed grey to coarsobles and slightly some c coarse,	sandy, gle, sub and boulde	ravelly ngular rrs. httly	2
Pit	Dime Length 5.00	ensions Pit Width 1.80	5	Pit Stability Sides stable ough 1.40m to	Shoring Used	Trench Co	omments	Remarks		Top 0.00	Backfill Base 3.80	Details Descrip Arisin	
Rema	orke			3.80m									



V	V	vhit	e the pos	rd sibilities	Address: 2 Main Stree BT39 9NE, UK Tel: (028) 9334 9351 Email: Info@whitefor Website: www.whitefo	dgeoservices	s.com		Tri	al F	Pit L	.og		
Projec	t Name:	Garrane Project- S.I.		roject No:	Client: Garrane	Green E	nergy Ltd		Date: 19/08/202	24				
				2177-22	Contractor: Wh	iteford G	eoservices	Ltd	Co-ords: E5550	02.58 N	1625873	3.51		
Locati	on:				Sub Contractor	:			Equipment: Hita	ichi ZAX	KIS 130	LCN		
Loc	cation No TP-S0			ion Type TP	Level 61.30m A	oD		jed By OR	Scale 1:25		1	age Numb Sheet 1 of		
Well	Water	Sample	and In	Situ Testing	Depth	Level	Legend		Stratum De	scriptio				
	Strikes	1.00 1.50 2.00 3.00	B B	Results	(m) 0.10 1.40 1.80	(m) 61.20 59.90 59.50		Soft to firr some cob coarse, su Stiff to ver CLAY, with	or firm, grey silty sandy gravelly CLAY, with cobbles and boulders. Gravel is fine to e, sub angular to sub rounded. Or very stiff, greyish brown, slightly sandy with some cobbles and boulders. Gravel or coarse, sub angular to sub rounded.					
													=	
		ensions		D" 01 1 1111		French Co	omments					II Details		
Pit !	Length 5.20	Pit Widtl 1.80		Pit Stability Sides Stable	Shoring Used			Remarks		Top 0.00	Base 3.80	Descri Arisi		
`	•												5	
Rema	arks													



reen Energy	: Garrane		whiteford explore the possibilities Project Name: Garrane										
ocation: Bally	i-Toject-	Project	t No:	Client: Garrane	Green E	nergy Ltd		Date: 27/09/202	22				
		ا.ن	2177	22	Contractor: Whi	teford Ge	eoservices	Ltd	Co-ords: E5545	65.00 N	625982	.00	
	ynagoul, (Co. Lim	erick		Sub Contractor:	tli group			Equipment: Hyu	ındai hx	140lc		
		Lo	cation Ty TP	ре	Level			ed By others	Scale 1:25			ge Numb neet 1 of	
Water Strikes			d In Situ		Depth (m)	Level (m)	Legend		Stratum De	scription	1		
Strikes	1.00 2.50		В	Results	(m) 0.25	(m)		sandy, slig cobble cor Sand is fin sub rounded. Stiff, brown with a med boulder co	tiff, brownish grey, sandy, gravelly SILT/CLAY ith a medium cobble, low boulder and low large oulder content. and is fine to coarse, Gravel is sub angular to ub rounded. Cobbles and boulders are sub ounded. End of Pit at 3.500m Backfill Detail marks Top Base Des				1 - 2 - 2
Dim Pit Length 4.00		Vidth 00	Pit Sta Sides ui upon cor	nstable	T Shoring Used None	rench Co	mments	Remarks		Top 0.00	Base	Details Descrip	



V	V	vhite explore	fo the pos	rd sibilities	Address: 2 Main Stree BT39 9NE, UK Tel: (028) 9334 9351 Email: Info@whiteford Website: www.whiteford				Tri	al P	it L	og	
Projec Green	t Name:	Garrane Project- S.I.	Р	roject No:	Client: Garrane	Green E	nergy Ltd		Date: 27/09/202	22			
orcon	Lifelgy	1 10,000-0.1.		2177-22	Contractor: Whi	teford Ge	eoservices	Ltd	Co-ords: E5543	69.00 N	626654.	00	
Location	on: Bally	nagoul, Co. Li			Sub Contractor:	tli group			Equipment: Hyu	ındai hx	140lc		
Loc	ation Nu TP-E	ımber		on Type TP	Level			ed By others	Scale 1:25			ge Numbo	
\ \ \ \ \ \ \ \ \ \	Water	Sample a		Situ Testing	Depth	Level		541010				001 1 01	
vveii	Strikes	Depth (m)	Туре	Results	(m)	(m)	Legend						
Well	Strikes	Depth (m) 0.50 1.50 2.50	ВВВ	Results	(m)		Legend A Company of the Company of t	Firm to stir sub round Stiff, brow with a men boulder co. Sand is fir sub round Stiff, brow of the sub round sub round. Loose to reach to coarse. Gravel is seen and to coarse.	ft to firm, grey mottled orange, slightly sandy, ghtly gravelly SILT with a low cobble content. Ind is fine to coarse, Gravel is sub angular to be rounded. Cobbles are sub rounded. In to stiff, grey, slightly sandy, slightly gravelly and is fine to coarse, Gravel is sub angular to be rounded. Cobbles are sub rounded. In the stiff, grey, slightly sandy, slightly gravelly are sub angular to be rounded. Cobbles are sub rounded. In the stiff, brownish grey, sandy, gravelly SILT/CLAY has medium cobble, low boulder and low large ulder content. In the stiff, brownish grey, sandy, gravelly SILT/CLAY has medium cobble, low boulder and low large ulder content. In the stiff, brownish grey, sandy, gravelly sub angular to be rounded. Cobbles and boulders are sub				
Pit l	Dime Length	nsions Pit Width 2.00	Si	Pit Stability ides unstable on completion	Shoring Used None	rench Co	mments	Remarks		Top 0.00	Backfill Base 3.60	Details Descrip Arisin	
Domo			up	on completion									

Remarks



V	V	vhite explore	e the pos	rd sibilities	Address: 2 Main Stree BT39 9NE, UK Tel: (028) 9334 9351 Email: Info@whiteford Website: www.whitefo				Tri	al F	Pit L	_og	
Projec	t Name:	Garrane Project- S.I.		roject No:	Client: Garrane	Green E	nergy Ltd		Date: 27/09/202	22			
Sieei	Lileigy	r roject- o.i.		2177-22	Contractor: Whi	iteford Ge	eoservices	Ltd	Co-ords: E5539	92.00 N	162669	8.00	
_ocati	on: Bally	nagoul, Co. L			Sub Contractor:	: tli group			Equipment: Hyu	ındai hx	140lc		
Lo	cation Nເ TP-D	ımber		on Type TP	Level			ed By others	Scale 1:25		1	age Numb Sheet 1 of	
Well	Water	Sample		'' Situ Testing	Depth	Level		Julio13		ccrintio		SHOOL 1 OI	
vveii	Strikes	Depth (m)	Туре	Results	(m)	(m)	Legend	David harass	Stratum De				
		2.00 3.00	ВВВВ	Results	0.20			Sand is fir sub round Firm to sti SILT with a Sand is fir sub round Stiff, brow with a med Sand is fir	htly gravelly SILT with a low cobble content. In to stiff, grey, slightly sandy, slightly gravelly in to stiff, grey, slightly sandy, slightly gravelly in the to coarse, Gravel is sub angular to rounded. Cobbles are sub rounded. If, brownish grey, sandy, gravelly SILT/CLAY in a medium cobble, low boulder content. In the to coarse, Gravel is sub angular to rounded. Cobbles and boulders are sub angular to rounded. Cobbles and boulders are sub inded. End of Pit at 3.500m				
Pit	Length	nsions Pit Width		Pit Stability	Shoring Used	rench Co	omments	Remarks		Тор	Base	III Details Descri	
Rema	4.00	2.00		ides unstable on completion	None					0.00	3.50	Arisir	ngs



		the pos	sibilities	Tel: (028) 9334 9351 Email: Info@whiteford Website: www.whitefo	lgeoservices rdgeoservic	s.com es.com		Iri	ai F	Pit L	.og
roject Name: reen Energy			0477.00	Client: Garrane				Date: 27/09/202			
				Contractor: Whi	teford Ge	eoservices	Ltd	Co-ords: E5545	52.00 N	1627352	.00
	nagoul, Co. L			Sub Contractor:	tli group		I.D	Equipment: Hyu	ındai hx		
Location No			on Type TP	Level			ed By thers	Scale 1:25		1	ge Number neet 1 of 1
Vell Water	Sample a	nd In	Situ Testing	Depth	Level	Legend		Stratum De	scriptio	า	
Vell Strikes	Depth (m) 0.50	В	Results	0.30	(m)	Legend	Soft to firm slightly grassand is firm sub round. Firm to stic CLAY with content. Sand is firm to stic CLAY with content.	n, slightly organi	c, sand range, s low co vel is si sub rou sandy, le and k	y, silty slightly sabble con ub angul nded. gravelly gravelly bw bould	SILT/ ler
•	3.00	В		2.80			to coarse	medium dense, s SAND with a low sub angular to su	cobble	content.	
Dime Pit Length 4.00	ensions Pit Width 2.00	Si	Pit Stability ides unstable	3.20 T Shoring Used None	rench Co		Remarks	End of Pit at	3.200m Top 0.00	Backfill Base 3.20	Details Descriptio Arisings
emarks		upo	on completion								

V	V	vhite explore	fo the poss	rd	Address: 2 Main Stree BT39 9NE, UK Tel: (028) 9334 9351 Email: Info@whiteford Website: www.whiteford		-		Tri	al P	it L	og	
Projec	t Name:	Garrane Project- S.I.		oject No:	Client: Garrane	Green E	nergy Ltd		Date: 27/09/202	22			
01001	Lilolgy	. 10,000 0	2	2177-22	Contractor: Whi	iteford Ge	eoservices	Ltd	Co-ords: E5539	923.00 N	627695.	00	
		nagoul, Co. Li			Sub Contractor:	: tli group			Equipment: Hyu	undai hx			
Lo	cation Nu TP-B	ımber		on Type P	Level			ed By others	Scale 1:25			ge Numboneet 1 of	
Well	Water	Sample a		Situ Testing		Level	Legend		Stratum De	escription			
~~~~	Strikes	Depth (m)	Туре	Results	(m)	(m)	Logona	Dark brow	n, slightly organi				
					0.20		****	TOPSOIL Soft to firm	n, grey mottled o	range, s	lightly sa	andy,	-
		0.50	В		0.90			Sand is fir sub round  Firm to stir SILT with a	ightly gravelly SILT with a low cobble content.  and is fine to coarse, Gravel is sub angular to ub rounded. Cobbles are sub rounded.  rm to stiff, grey, slightly sandy, slightly gravelly LT with a low cobble content.  and is fine to coarse, Gravel is sub angular to ub rounded. Cobbles are sub rounded.				
					2.30			Stiff, brow with a med	Stiff, brownish grey, sandy, gravelly SILT/CLAY with a medium cobble, low boulder content.				
		3.00	В						ith a medium cobble, low boulder content.  and is fine to coarse, Gravel is sub angular to ub rounded. Cobbles and boulders are sub				3
					3.50				End of Pit a	t 3.500m			4 -
Dit		ensions Pit Width		Pit Stahility	Shoring Used	rench Co	mments	Remarks		Тор	Backfill Base	Details Descrip	otion
•	Pit Length Pit Width Pit Stability 4.00 2.00 Sides unstable upon completio			des unstable	None			Remarks		0.00	3.50	Descrip Arisin	

Remarks



whiteford explore the possibilities Project Name: Garrane					rd sibilities	Address: 2 Main Stre BT39 9NE, UK Tel: (028) 9334 9351 Email: Info@whitefor Website: www.whitef				Tri	al F	it L	og	
rojec	t Name:	Garrane Project-	S I	Р	roject No:	Client: Garrane	e Green E	nergy Ltd		Date: 27/09/202	22			
лееі	Elleigy	riojeci-	S.I.		2177-22	Contractor: Wh	niteford Ge	eoservices	Ltd	Co-ords: E5536	44.00 N	1627478	.00	
.ocati	on: Bally	nagoul, (	Co. Lii	meric	<	Sub Contracto	r: tli group	ı		Equipment: Hyu	ındai hx	140lc		
Lo	cation Nu	ımber			on Type TP	Level			jed By others	Scale 1:25		1	ge Numbeneet 1 of 2	
Well	Water Strikes	Sam Depth			Situ Testing Results	(m)	Level (m)	Legend		Stratum De	scription	า		
				Type	resuits	0.45			TOPSOIL					-
		2.50		В		2.00			Soft to firm, grey mottled orange, slightly sandy slightly gravelly SILT with a low cobble content.  Sand is fine to coarse, Gravel is sub angular to sub rounded. Cobbles are sub rounded.  Firm to stiff, grey, slightly sandy, slightly gravelly SILT with a low cobble content.  Sand is fine to coarse, Gravel is sub angular to sub rounded. Cobbles are sub rounded.			ar to	2 - 3 - 3 - 3	
						3.40			with a me	iff, brownish grey, sandy, gravelly SILT/CLAY th a medium cobble, low boulder content.  and is fine to coarse, Gravel is sub angular to b rounded. Cobbles and boulders are sub unded.  End of Pit at 3.600m				4
Di+	<b>Dime</b> Length	nsions	Vidth		Pit Stability	Shoring Used	Trench Co	mments	Remarks		Тор	Backfil Base	<b>Details</b> Descrip	ntion
1 10	4.00		00	Sid	es stable upon completion	None			Comans		0.00	3.60	Arisin	
Rema	arks	1				t .	1							



#### 2177-22 - Garrane Green Energy Project Preliminary Data of Peat Depth Variation Across the Site

Location	Easting	Northing	Depth
1	553641	627475	0
2	553921	627685	0
3	554267	627779	0
4	554338	627570	0
5	553979	627331	0
6	554111	627129	0
7	554454	627324	0
8	554406	627003	0
9	554032	626747	0
10	554352	626620	0
11	554442	626284	0
12	554587	625974	0



## APPENDIX C INTERPRETED GEOPHYSICAL SURVEY DATA

Annotated Electrical Resistivity Tomography (ERT) Profiles:


T1	1 x A3
T2	1 x A3
Т3	1 x A3
T4	1 x A3
T5	1 x A3
T6	1 x A3
T7	1 x A3
Т8	1 x A3
Т9	1 x A3
MET MAST	1 x A3




#### 2177-22 Garrane Green Energy Project **Turbine T1**

### **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbine T1 23rd August 2024





#### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



**Natural Soils** (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone (Massive or partially weathered)

- 1. All depths are relative to ground level existing at the time of the
- survey / investigation.

  2. Positions, where detailed, relate to the IG coordinate system.

  3. Please refer to Drawing 2217-23-A for position of each ERT Profile.

Draft


J.M. - 18/06/2025 2177/22 - ERT-T1 18/06/2025 As Shown J.W. Interpreted Electrical Resistivity Data Profiles T01-1 and T01-2 at Turbin T1


Garrane Green Energy Project

#### 2177-22 Garrane Green Energy Project **Turbine T2**

### **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbine T2 23rd August 2024





#### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



**Organic Soils** (PEAT and sandy, organic SILT / CLAYS)



(Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone (Massive or partially weathered)

- 1. All depths are relative to ground level existing at the time of the
- survey / investigation.

  2. Positions, where detailed, relate to the IG coordinate system.

  3. Please refer to Drawing 2217-23-A for position of each ERT Profile.


Draft


J.W.		J.W.	J.M 18/06/2		ing No. /22 - ERT-T2	18/06/2025	As Sho
Whiteford G	eoservices Lta			Interpreted Electrical Resistivity Data			

Garrane Green Energy Project

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbines T3 23rd August 2024





### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



**Natural Soils** (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** 



(Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone (Massive or partially weathered)

- 1. All depths are relative to ground level existing at the time of the
- survey / investigation.

  2. Positions, where detailed, relate to the IG coordinate system.


  3. Please refer to Drawing 2217-23-A for position of each ERT Profile.


Draft

J.M. - 18/06/2025 2177/22 - ERT-T3 18/06/2025 As Shown J.W. Interpreted Electrical Resistivity Data Profiles T03-1 and T03-2 at Turbine T3

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles Turbine T4 23rd August 2024





## **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



**Natural Soils** (Sandy, gravelly CLAYS with cobbles and boulders)



Highly Degraded Limestone (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone (Massive or partially weathered)

- 1. All depths are relative to ground level existing at the time of the
- survey / investigation.

  2. Positions, where detailed, relate to the IG coordinate system.


  3. Please refer to Drawing 2217-23-A for position of each ERT Profile.


Draft

J.M. - 18/06/2025 2177/22 - ERT-T4 18/06/2025 As Shown J.W. Interpreted Electrical Resistivity Data Profiles T04-1 and T04-2 at Turbine T4

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbine T5 23rd August 2024





### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



Natural Soils (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



(Massive or partially weathered)

- 1. All depths are relative to ground level existing at the time of the
- survey / investigation.

  2. Positions, where detailed, relate to the IG coordinate system.


  3. Please refer to Drawing 2217-23-A for position of each ERT Profile.


Draft

J.M. - 18/06/2025 2177/22 - ERT-T5 18/06/2025 Interpreted Electrical Resistivity Data
Profiles T05-1 and T05-2 at Turbine T5

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbine T6 23rd August 2024





## **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



Natural Soils (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone (Massive or partially weathered)

Draft

gned by	Checked by	Approved by - date		Drawing No.	Date	Scale
J.W.	J.W.	J.M 1	8/06/2025	2177/22 - ERT-T6	18/06/2025	As Shown
hiteford Geoservices	Ltd		Interprete	d Electrical Re	esistivity Data	

Profiles T06-1 and T06-2 at Turbine T6 Garrane Green Energy Project

^{1.} All depths are relative to ground level existing at the time of the


survey / investigation.


2. Positions, where detailed, relate to the IG coordinate system.

3. Please refer to Drawing 2217-23-A for position of each ERT Profile.

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbine T7 23rd August 2024





### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



**Natural Soils** (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone (Massive or partially weathered)

Draft

J.M. - 18/06/2025 2177/22 - ERT-T7 18/06/2025 As Shown Interpreted Electrical Resistivity Data Profiles T07-1 and T07-2 at Turbine T7

^{1.} All depths are relative to ground level existing at the time of the


survey / investigation.


2. Positions, where detailed, relate to the IG coordinate system.

3. Please refer to Drawing 2217-23-A for position of each ERT Profile.

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbine T8 23rd August 2024





### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



Natural Soils (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone (Massive or partially weathered)

J.M. - 18/06/2025 2177/22 - ERT-T8 18/06/2025 Interpreted Electrical Resistivity Data
Profiles T08-1 and T08-2 at Turbine T8 Garrane Green Energy Project

^{1.} All depths are relative to ground level existing at the time of the


survey / investigation.


2. Positions, where detailed, relate to the IG coordinate system.

3. Please refer to Drawing 2217-23-A for position of each ERT Profile.

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Turbine T9 23rd August 2024





### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



Natural Soils (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Degraded Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as a raft of dense boulders.)



Limestone

(Massive or partially weathered)

- 1. All depths are relative to ground level existing at the time of the
- survey / investigation.

  2. Positions, where detailed, relate to the IG coordinate system.

  3. Please refer to Drawing 2217-23-A for position of each ERT Profile.

Draft


J.W.


J.M. - 18/06/2025 2177/22 - ERT-T9 18/06/2025 As Shown Interpreted Electrical Resistivity Data
Profiles T09-1 and T09-2 at Turbine T9

### 2177-22 Garrane Green Energy Project Met Mast MM

## **Electrical Resistivity Tomography (ERT) Surveys**

Interpretated Resistivity Imaging Profiles at Met Mast MM 23rd August 2024





### **Key To Sections**

**Each Profile indicates variation** in the elctrical restivity of the Subsurface with depth.

Natural Soils (generally 10 - 500Wm) Rock (generally >500Wm)



Organic Soils (PEAT and sandy, organic SILT / CLAYS)



**Natural Soils** (Sandy, gravelly CLAYS with cobbles and boulders)



**Highly Fractured Limestone** (Probably deeply weathered or highly fractured Limestone rock. May include wide, soil filled, fractures or appears as



Limestone (Massive or partially weathered)

a raft of dense boulders.)

- 1. All depths are relative to ground level existing at the time of the
- survey / investigation.

  2. Positions, where detailed, relate to the IG coordinate system.

  3. Please refer to Drawing 2217-23-A for position of each ERT Profile.

Draft

J.M. - 18/06/2025 2177/22 - ERT-MM 18/06/2025 As Shown Interpreted Electrical Resistivity Data Profiles MM-1 and MM-2 at Met Mast MM Garrane Green Energy Project

# APPENDIX D LABORATORY TESTING RESULTS

Atterberg Limits	1 x A4
Bulk Density and Dry Density	1 x A4
Bulk Density	1 x A4
Natural Moisture Content	1 x A4
Partial Size Distribution	10 x A4
Sulphate Content of Water Extract, Chloride Content of Water	9 x A4
Extract, Sulphide Content of Water Extract & pH	




### **Atterberg Limits**

**Location: Garrane Green Energy Project** 

**Client: Garrane Green Energy Ltd** 

Job No: 2177-22

TP SO4



Operator

SV

TESTS CARRIED OUT BY DR SIVAKUMAR VINAYAGAMOTHY OF QUEENS UNIVERSITY BELFAST

Refer to Log

Checked

JM



Approved JW

## **Bulk Density**



**Location: Garrane Green Energy Project** 

Client: Garrane Green Energy Ltd

Job No: 2177-22

Hole ID	Depth	Bulk Density (kg/m³)
TP SO1	1.50	2211
TP SO2	2.00	2302
TP SO3	1.20	2248
TP SO4	2.70	2313

Operator	Checked	Approved
DR. SIVAKUMAR	JMcN	JW

Test Method: BS 1377 : 1990: Part 2

Queens University Belfast

## **Laboratory Results**



**Location: Garrane Green Energy Project** 

Job No: 2177-22

Client: Garrane Green Energy Ltd

Sample no:	Depth (m)	Water Content (%)	Bulk Density kg/m3	Dry Density kg/m3
TP-A	2.50	27.7	2082	1500
TP-B	1.50	26.4	2098	1506
TP-C	3.00	11.0	2251	2041
TP-D	3.0	10.5	2492	2045
TP-E	3.5	14.4	2439	2062
TP-F	2.5	12.9	2392	1967

Operator	Checked	Approved
LJ	JMCN	JW

### **Moisture Content**



**Location: Garrane Green Energy Project** 

Client: Garrane Green Energy Ltd

Job No: 2177-22

Hole ID	Depth	Moisture Content %
TP SO1	1.50	11.0
TP SO2	2.00	7.9
TP SO3	1.20	8.9
TP SO4	2.70	8.2

Operator	Checked	Approved
DR. SIVAKUMAR	JMcN	JW

Test Method: BS 1377 : 1990: Part 2

Queens University Belfast



**Element Materials Technology** 

Unit 3 Deeside Point

Zone 3

Deeside Industrial Park

Deeside

CH5 2UA

P: +44 (0) 1244 833780

F: +44 (0) 1244 833781

W: www.element.com

Whiteford Geoservices Straid House Straid Ballyclare United Kingdom BT39 9EU







Attention: Joy McNeill

Date: 9th September, 2024

Your reference : 2177-22

Our reference : Test Report 24/15197 Batch 1

Location : Garrane Green Energy Project

Date samples received : 5th September, 2024

Status : Final Report

Issue: 202409091334

Four samples were received for analysis on 5th September, 2024 of which four were scheduled for analysis. Please find attached our Test Report which should be read with notes at the end of the report and should include all sections if reproduced. Interpretations and opinions are outside the scope of any accreditation, and all results relate only to samples supplied.

All analysis is carried out on as received samples and reported on a dry weight basis unless stated otherwise. Results are not surrogate corrected.

The greenhouse gas emissions generated (in Carbon - Co2e) to obtain the results in this report are estimated as:

Scope 1&2 emissions - 4.923 kg of CO2

Scope 1&2&3 emissions - 11.635 kg of CO2

Authorised By:

**Bruce Leslie** 

Project Manager

Please include all sections of this report if it is reproduced

### **Element Materials Technology**

Client Name: Whiteford Geoservices

Reference: 2177-22
Location: Garrane WF
Contact: Joy McNeill

Report : Solid

Solids: V=60g VOC jar, J=250g glass jar, T=plastic tub

Contact: Joy McNeil EMT Job No: 24/15197

EMT Job No:	24/15197							_		
EMT Sample No.	1	2	3	4						
Sample ID	TPS01	TPS02	TPS03	TPS04						
Depth	1.50	2.00	1.20	2.74				Please se	e attached n	otes for all
COC No / misc								abbrevi	ations and a	cronyms
Containers	J	J	J	J						
Sample Date	04/09/2024	04/09/2024	04/09/2024	04/09/2024						
Sample Type	Soil	Soil	Soil	Soil						
Batch Number	1	1	1	1						Method
Date of Receipt	05/09/2024	05/09/2024	05/09/2024	05/09/2024				LOD/LOR	Units	No.
Natural Moisture Content	10.2	8.5	9.6	9.8				<0.1	%	PM4/PM0
*								_		
Chloride # Sulphate as SO4 (2:1 Ext) #	20 0.0052	22 0.0146	19 0.0035	20 0.0125				<2 <0.0015	mg/kg g/l	TM38/PM20 TM38/PM20
								.5.50.10	a.	
Sulphide	<10	<10	<10	<10				<10	mg/kg	TM107/PM45
рН#	8.81	9.06	8.96	8.97				<0.01	pH units	TM73/PM11
рн	0.01	9.06	0.90	0.97				<0.01	pri units	TIVIT 3/FIVITI

Client Name: Whiteford Geoservices

Reference: 2177-22
Location: Garrane WF
Contact: Joy McNeill

EMT Job No.	Batch	Sample ID	Depth	EMT Sample No.	Analysis	Reason			
	No deviating sample report results for job 24/15197								

Please note that only samples that are deviating are mentioned in this report. If no samples are listed it is because none were deviating. Only analyses which are accredited are recorded as deviating if set criteria are not met.

It is a requirement under ISO 17025 that we inform clients if samples are deviating i.e. outside what is expected. A deviating sample indicates that the sample 'may' be compromised but not necessarily will be compromised. The result is still accredited and our analytical reports will still show accreditation on the relevant analytes.

### NOTES TO ACCOMPANY ALL SCHEDULES AND REPORTS

**EMT Job No.:** 24/15197

#### **SOILS and ASH**

Please note we are only MCERTS accredited (UK soils only) for sand, loam and clay and any other matrix is outside our scope of accreditation.

Where an MCERTS report has been requested, you will be notified within 48 hours of any samples that have been identified as being outside our MCERTS scope. As validation has been performed on clay, sand and loam, only samples that are predominantly these matrices, or combinations of them will be within our MCERTS scope. If samples are not one of a combination of the above matrices they will not be marked as MCERTS accredited.

It is assumed that you have taken representative samples on site and require analysis on a representative subsample. Stones will generally be included unless we are requested to remove them.

All samples will be discarded one month after the date of reporting, unless we are instructed to the contrary. Asbestos samples are retained for 6 months.

If you have not already done so, please send us a purchase order if this is required by your company.

Where appropriate please make sure that our detection limits are suitable for your needs, if they are not, please notify us immediately.

All analysis is reported on a dry weight basis unless stated otherwise. Limits of detection for analyses carried out on as received samples are not moisture content corrected. Results are not surrogate corrected. Samples are dried at 35°C ±5°C unless otherwise stated. Moisture content for CEN Leachate tests are dried at 105°C ±5°C. Ash samples are dried at 35°C ±5°C.

Where Mineral Oil is quoted, this refers to Total Aliphatics C10-C40.

Where a CEN 10:1 ZERO Headspace VOC test has been carried out, a 10:1 ratio of water to wet (as received) soil has been used.

% Asbestos in Asbestos Containing Materials (ACMs) is determined by reference to HSG 264 The Survey Guide - Appendix 2 : ACMs in buildings listed in order of ease of fibre release.

Sufficient amount of sample must be received to carry out the testing specified. Where an insufficient amount of sample has been received the testing may not meet the requirements of our accredited methods, as such accreditation may be removed.

Negative Neutralization Potential (NP) values are obtained when the volume of NaOH (0.1N) titrated (pH 8.3) is greater than the volume of HCI (1N) to reduce the pH of the sample to 2.0 - 2.5. Any negative NP values are corrected to 0.

The calculation of Pyrite content assumes that all oxidisable sulphides present in the sample are pyrite. This may not be the case. The calculation may be an overesitimate when other sulphides such as Barite (Barium Sulphate) are present.

#### **WATERS**

Please note we are not a UK Drinking Water Inspectorate (DWI) Approved Laboratory .

ISO17025 accreditation applies to surface water and groundwater and usually one other matrix which is analysis specific, any other liquids are outside our scope of accreditation.

As surface waters require different sample preparation to groundwaters the laboratory must be informed of the water type when submitting samples.

Where Mineral Oil is guoted, this refers to Total Aliphatics C10-C40.

#### STACK EMISSIONS

Where an MCERTS report has been requested, you will be notified within 48 hours of any samples that have been identified as being outside our MCERTS scope. As validation for Dioxins and Furans and Dioxin like PCBs has been performed on XAD-2 Resin, only samples which use this resin will be within our MCERTS scope.

Where appropriate please make sure that our detection limits are suitable for your needs, if they are not, please notify us immediately.

#### **DEVIATING SAMPLES**

All samples should be submitted to the laboratory in suitable containers with sufficient ice packs to sustain an appropriate temperature for the requested analysis. The temperature of sample receipt is recorded on the confirmation schedules in order that the client can make an informed decision as to whether testing should still be undertaken.

#### **SURROGATES**

Surrogate compounds are added during the preparation process to monitor recovery of analytes. However low recovery in soils is often due to peat, clay or other organic rich matrices. For waters this can be due to oxidants, surfactants, organic rich sediments or remediation fluids. Acceptable limits for most organic methods are 70 - 130% and for VOCs are 50 - 150%. When surrogate recoveries are outside the performance criteria but the associated AQC passes this is assumed to be due to matrix effect. Results are not surrogate corrected.

### DILUTIONS

A dilution suffix indicates a dilution has been performed and the reported result takes this into account. No further calculation is required.

#### **BLANKS**

Where analytes have been found in the blank, the sample will be treated in accordance with our laboratory procedure for dealing with contaminated blanks.

**EMT Job No.:** 24/15197

#### NOTE

Data is only reported if the laboratory is confident that the data is a true reflection of the samples analysed. Data is only reported as accredited when all the requirements of our Quality System have been met. In certain circumstances where all the requirements of the Quality System have not been met, for instance if the associated AQC has failed, the reason is fully investigated and documented. The sample data is then evaluated alongside the other quality control checks performed during analysis to determine its suitability. Following this evaluation, provided the sample results have not been effected, the data is reported but accreditation is removed. It is a requirement of our Accreditation Body for data not reported as accredited to be considered indicative only, but this does not mean the data is not valid.

Where possible, and if requested, samples will be re-extracted and a revised report issued with accredited results. Please do not hesitate to contact the laboratory if further details are required of the circumstances which have led to the removal of accreditation.

Laboratory records are kept for a period of no less than 6 years.

#### REPORTS FROM THE SOUTH AFRICA LABORATORY

Any method number not prefixed with SA has been undertaken in our UK laboratory unless reported as subcontracted.

#### **Measurement Uncertainty**

Measurement uncertainty defines the range of values that could reasonably be attributed to the measured quantity. This range of values has not been included within the reported results. Uncertainty expressed as a percentage can be provided upon request.

#### **Customer Provided Information**

Sample ID and depth is information provided by the customer.

#### Age of Diesel

The age of release estimation is based on the nC17/pristane ratio only as prescribed by Christensen and Larsen (1993) and Kaplan, Galperin, Alimi et al., (1996).

Age estimation should be treated with caution as it can be influenced by site specific factors of which the laboratory are not aware.

#### **Tentatively Identified Compounds (TICs)**

Where Tentatively Identified Compounds (TICs) are reported, up to 10 Tentatively Identified Compounds will be listed where there is found to be a greater than 80% match with the NIST library. The reported concentration is determined semi-quantitively, with a matrix specific limit of detection. Note, other compounds may be present but are not reported.

### **ABBREVIATIONS and ACRONYMS USED**

<b>I</b>	
#	ISO17025 (UKAS Ref No. 4225) accredited - UK.
SA	ISO17025 (SANAS Ref No.T0729) accredited - South Africa
В	Indicates analyte found in associated method blank.
DR	Dilution required.
М	MCERTS accredited.
NA	Not applicable
NAD	No Asbestos Detected.
ND	None Detected (usually refers to VOC and/SVOC TICs).
NDP	No Determination Possible
SS	Calibrated against a single substance
SV	Surrogate recovery outside performance criteria. This may be due to a matrix effect.
W	Results expressed on as received basis.
+	AQC failure, accreditation has been removed from this result, if appropriate, see 'Note' on previous page.
>>	Results above quantitative calibration range. The result should be considered the minimum value and is indicative only. The actual result could be significantly higher.
*	Analysis subcontracted to an Element Materials Technology approved laboratory.
СО	Suspected carry over
LOD/LOR	Limit of Detection (Limit of Reporting) in line with ISO 17025 and MCERTS
ME	Matrix Effect
NFD	No Fibres Detected
BS	AQC Sample
LB	Blank Sample
N	Client Sample
ТВ	Trip Blank Sample
ОС	Outside Calibration Range

### **HWOL ACRONYMS AND OPERATORS USED**

HS	Headspace Analysis.
EH	Extractable Hydrocarbons - i.e. everything extracted by the solvent.
CU	Clean-up - e.g. by florisil, silica gel.
1D	GC - Single coil gas chromatography.
Total	Aliphatics & Aromatics.
AL	Aliphatics only.
AR	Aromatics only.
2D	GC-GC - Double coil gas chromatography.
#1	EH_Total but with humics mathematically subtracted
#2	EU_Total but with fatty acids mathematically subtracted
_	Operator - underscore to separate acronyms (exception for +).
+	Operator to indicate cumulative e.g. EH+HS_Total or EH_CU+HS_Total
MS	Mass Spectrometry.


**EMT Job No**: 24/15197

Test Method No.	Description	Prep Method No. (if appropriate)	Description	ISO 17025 (UKAS/S ANAS)	MCERTS (UK soils only)	Analysis done on As Received (AR) or Dried (AD)	Reported on dry weight basis
PM4	Gravimetric measurement of Natural Moisture Content and % Moisture Content at either 35°C or 105°C. Calculation based on ISO 11465:1993(E) and BS1377-2:1990.	PM0	No preparation is required.			AR	
TM38	Soluble Ion analysis using Discrete Analyser. Modified US EPA methods: Chloride 325.2 (1978), Sulphate 375.4 (Rev.2 1993), O-Phosphate 365.2 (Rev.2 1993), TON 353.1 (Rev.2 1993), Nitrite 354.1 (1971), Hex Cr 7196A (1992), NH4+ 350.1 (Rev.2 1993) – All anions comparable to BS ISO 15923-1: 2013I	PM20	Extraction of dried and ground or as received samples with deionised water in a 2:1 water to solid ratio using a reciprocal shaker for all analytes except hexavalent chromium. Extraction of as received sample using 10:1 ratio of 0.2M sodium hydroxide to soil for hexavalent chromium using a reciprocal shaker.	Yes		AD	Yes
TM73	Modified US EPA methods 150.1 (1982) and 9045D Rev. 4 - 2004) and BS1377-3:1990. Determination of pH by Metrohm automated probe analyser.	PM11	Extraction of as received solid samples using one part solid to 2.5 parts deionised water.	Yes		AR	No
TM107	Determination of Sulphide/Thiocyanate by Skalar Continuous Flow Analyser	PM45	As received solid samples are extracted with 1M NaOH by orbital shaker for Cyanide, Sulphide and Thiocyanate analysis.			AR	Yes

#### Sieve % Size mm Passing 125.000 100.0 75.000 100.0 63.000 100.0 50.000 100.0 37.500 90.0 28.000 90.0 20.000 90.0 14.000 86.6 10.000 83.9 6.300 81.4 5.000 74.3 71.3 3.350 2.000 68.0 1.180 65.1 0.600 61.2 0.425 58.7 55.0 0.300 0.212 48.4 0.150 42.3 0.063 37.5

### **Determination of Particle Size Distribution**

BS 1377: 1990: Part 2: Clauses 9.2 & 9.5



#### Percentage Particle Size

Clay	Fine Medium Coarse	Fine Medium Coarse	Fine Medium Coarse	Cobbles	Boulder
	Silt	Sand	Gravel		
0.0	37.5	30.6	32.0	0.0	0.0

Date sample tested

٧S

Sample Description Gravelly sandy SILT

Operator

Project No. BH/TP No.

2177-22 TP-S01

**Project** Garrane Green Energy Project Approved Checked

Sample No.


07/09/2024 Depth

1.5m

#### Sieve % Size mm Passing 125.000 100.0 75.000 100.0 63.000 100.0 50.000 100.0 37.500 100.0 28.000 100.0 20.000 98.2 14.000 95.0 10.000 92.1 6.300 90.0 5.000 83.5 3.350 80.1 2.000 75.8 1.180 72.2 0.600 66.7 0.425 63.7 59.3 0.300 52.5 0.212 0.150 47.1 0.063 43.0

### **Determination of Particle Size Distribution**

BS 1377: 1990: Part 2: Clauses 9.2 & 9.5



#### Percentage Particle Size

Clay	Fine Medium Coarse	Fine Medium Coarse	Fine Medium Coarse	Cobbles	Boulder
	Silt	Sand	Gravel		
0.0	43.0	32.8	24.2	0.0	0.0

Sample Description Gravelly sandy SILT

Project No. BH/TP No. 2177-22 TP-S02

Project Garrane Green Energy Project
SS Checked VS Approved

Operator

VS Date sample tested 07/09/2024 Depth


Sample No.

2.0m

#### Sieve % Size mm Passing 125.000 100.0 75.000 100.0 100.0 63.000 50.000 100.0 37.500 100.0 28.000 86.7 20.000 86.7 14.000 84.4 10.000 82.2 6.300 79.5 5.000 73.9 71.1 3.350 2.000 67.8 1.180 64.6 0.600 60.1 0.425 57.4 0.300 52.9 0.212 46.7 0.150 41.5 0.063 36.5

### **Determination of Particle Size Distribution**

BS 1377: 1990: Part 2: Clauses 9.2 & 9.5



### Percentage Particle Size

Clay	Fine Medium Coarse	Fine Medium Coarse	Fine Medium Coarse	Cobbles	Boulder
	Silt	Sand	Gravel		
0.0	36.5	31.3	32.2	0.0	0.0

Sample Description Gravelly sandy SILT

Project No. 2177-22 BH/TP No. TP-S03


1.2m

	Project	Garrane (	Green Energy	/ Project			Sample No.
Operator	SS	Checked	VS	Approved	VS	Date sample tested	07/09/2024 Depth

#### Sieve % Size mm Passing 125.000 100.0 75.000 100.0 63.000 100.0 50.000 100.0 37.500 100.0 28.000 91.3 20.000 87.7 14.000 83.6 10.000 79.9 6.300 78.3 5.000 72.1 3.350 69.2 2.000 65.9 1.180 62.6 0.600 58.0 0.425 54.5 49.2 0.300 0.212 43.8 41.0 0.150 0.063 37.8

### **Determination of Particle Size Distribution**

BS 1377: 1990: Part 2: Clauses 9.2 & 9.5



#### Percentage Particle Size

Clay	Fine Medium Coarse	Fine Medium Coarse	Fine Medium Coarse	Cobbles	Boulder
	Silt	Sand	Gravel		
0.0	37.8	28.1	34.1	0.0	0.0

Date sample tested

Sample Description Gravelly sandy SILT

Operator

Project No. BH/TP No.

2177-22 TP-S04


**Project** Garrane Green Energy Project Approved ٧S Checked

Sample No.

07/09/2024 Depth

2.7m


Location: Garrane Green Energy Project			Job ref:	2177-22
			Borehole/	
			Pit no.	TP-A
Soil description: SLIT / CLAY			Sample no.	
			Depth	2.50
Test method BS 1377-2:1990:9.2/9.3/9.4/9.5*			Date	28.10.22
Initial dry mass (m1)	2082.00			
Mass of receiver (g)				
BS test sieve (mm)	Mass of dry soil + receiver (g)	Mass of dry soil retained (m2) (g)	Percentage retained (m2/m1)100	Cumulative percentage passing
75		0.00	0.00	100.00
50		0.00	0.00	100.00
37.5		0.00	0.00	100.00
20		0.00	0.00	100.00
14		0.00	0.00	100.00
10		0.00	0.00	100.00
6.3		2.40	0.12	99.88
5		1.20	0.06	99.83
2		4.50	0.22	99.61
1.18		2.90	0.14	99.47
0.6		3.60	0.17	99.30
0.425		2.50	0.12	99.18
0.212		7.10	0.34	98.84
0.15		5.80	0.28	98.56
0.063		5.70	0.27	98.29
Bottom tray		2046.30	98.29	0.00





Operator	Checked	Approved
LJ	JMcN	JW


Location: Garrane Green Energy Project			Job ref:	2177-22
			Borehole/	
			Pit no.	TP-B
Soil description: Slightly Sandy SILT / CLAY			Sample no.	
			Depth	1.50
Test method BS 1377-2:1990:9.2/9.3/9.4/9.5*			Date	28.10.22
Initial dry mass (m1)	2043.30			
Mass of receiver (g)				
BS test sieve (mm)	Mass of dry soil + receiver (g)	Mass of dry soil retained (m2) (g)	Percentage retained (m2/m1)100	Cumulative percentage passing
75		0.00	0.00	100.00
50		0.00	0.00	100.00
37.5		0.00	0.00	100.00
20		0.00	0.00	100.00
14		0.00	0.00	100.00
10		1.00	0.05	99.95
6.3		4.20	0.21	99.75
5		1.60	0.08	99.67
2		9.50	0.46	99.20
1.18		6.70	0.33	98.87
0.6		11.40	0.56	98.32
0.425		10.20	0.50	97.82
0.212		26.60	1.30	96.52
0.15		11.50	0.56	95.95
0.063		14.10	0.69	95.26
Bottom tray		1946.50	95.26	0.00





Operator	Checked	Approved
LJ	JMcN	JW


Location: Garrane Green Energy Project			Job ref:	2177-22
			Borehole/	
			Pit no.	TP-C
Soil description: Slightly Gravelly, Sandy, Sl	LT / CLAY		Sample no.	
			Depth	3.00
Test method BS 1377-2:1990:9.2/9.3/9.4/9.5*			Date	28.10.22
nitial dry mass (m1)	1744.10			
Mass of receiver (g)				
BS test sieve (mm)	Mass of dry soil + receiver (g)	Mass of dry soil retained (m2) (g)	Percentage retained (m2/m1)100	Cumulative percentage passing
75		0.00	0.00	100.00
50		0.00	0.00	100.00
37.5		0.00	0.00	100.00
20		11.30	0.65	99.35
14		13.40	0.77	98.58
10		44.60	2.56	96.03
6.3		68.00	3.90	92.13
5		40.90	2.35	89.78
2		186.00	10.66	79.12
1.18		161.70	9.27	69.85
0.6		297.10	17.03	52.81
0.425		247.80	14.21	38.60
0.212		71.40	4.09	34.51
0.15		80.60	4.62	29.89
0.063		5.70	0.33	29.56
Bottom tray		515.60	29.56	0.00





Operator	Checked	Approved
LJ	JMcN	JW


Location: Garrane Green Energy Project			Job ref:	2177-22
			Borehole/	
			Pit no.	TP-D
Soil description: Slightly Gravelly, Sandy, Cl	_AY / SILT		Sample no.	
			Depth	3.00
Test method BS 1377-2:1990:9.2/9.3/9.4/9.5*			Date	28.10.22
Initial dry mass (m1)	2304.90			
Mass of receiver (g)				
BS test sieve (mm)	Mass of dry soil + receiver (g)	Mass of dry soil retained (m2) (g)	Percentage retained (m2/m1)100	Cumulative percentage passing
75		0.00	0.00	100.00
50		0.00	0.00	100.00
37.5		0.00	0.00	100.00
20		73.00	3.17	96.83
14		58.50	2.54	94.29
10		101.80	4.42	89.88
6.3		91.00	3.95	85.93
5		55.20	2.39	83.54
2		157.70	6.84	76.69
1.18		86.50	3.75	72.94
0.6		119.00	5.16	67.78
0.425		147.00	6.38	61.40
0.212		255.80	11.10	50.30
0.15		93.30	4.05	46.25
0.063		121.00	5.25	41.00
Bottom tray		945.10	41.00	0.00





Operator	Checked	Approved
LJ	JMcN	JW


Location: Garrane Green Energy Project			Job ref:	2177-22
			Borehole/	
			Pit no.	TP-E
Soil description:Slightly Gravelly, Very Sand	y CLAY / SILT		Sample no.	
			Depth	3.50
Test method BS 1377-2:1990:9.2/9.3/9.4/9.5*			Date	28.10.22
Initial dry mass (m1)	2270.20			
Mass of receiver (g)				
BS test sieve (mm)	Mass of dry soil + receiver (g)	Mass of dry soil retained (m2) (g)	Percentage retained (m2/m1)100	Cumulative percentage passing
75		0.00	0.00	100.00
50		0.00	0.00	100.00
37.5		0.00	0.00	100.00
20		0.00	0.00	100.00
14		50.10	2.21	97.79
10		30.90	1.36	96.43
6.3		46.20	2.04	94.40
5		39.10	1.72	92.67
2		132.30	5.83	86.85
1.18		73.90	3.26	83.59
0.6		110.20	4.85	78.74
0.425		138.90	6.12	72.62
0.212		529.10	23.31	49.31
0.15		225.90	9.95	39.36
0.063		158.30	6.97	32.39
Bottom tray		735.30	32.39	0.00





Operator	Checked	Approved
LJ	JMcN	JW

Location: Garrane Green Energy Project			Job ref:	2177-22
			Borehole/	
			Pit no.	TP-F
Soil description: Slightly gravelly, Sandy, Sl	LT / CLAY		Sample no.	
			Depth	2.50
Test method BS 1377-2:1990:9.2/9.3/9.4/9.5*			Date	28.10.22
Initial dry mass (m1)	2636.40			
Mass of receiver (g)				
BS test sieve (mm)	Mass of dry soil + receiver (g)	Mass of dry soil retained (m2) (g)	Percentage retained (m2/m1)100	Cumulative percentage passing
75		0.00	0.00	100.00
50		0.00	0.00	100.00
37.5		0.00	0.00	100.00
20		80.70	3.06	96.94
14		78.40	2.97	93.97
10		114.10	4.33	89.64
6.3		114.20	4.33	85.31
5		66.90	2.54	82.77
2		187.70	7.12	75.65
1.18		96.20	3.65	72.00
0.6		136.30	5.17	66.83
0.425		115.70	4.39	62.44
0.212		357.20	13.55	48.89
0.15		94.80	3.60	45.30
0.063		121.80	4.62	40.68
Bottom tray		1072.40	40.68	0.00





Operator	Checked	Approved
LJ	JMcN	JW

## **Chemical Content Results**



**Location: Garrane Green Energy Project** 

Job No: 2177-22

Client: Garrane Green Energy Ltd

Sample ID:	Depth (m)	Sulphate (mg/l)	Chloride (mg/l)	Sulphide (mg/l)	рН
TP-A	2.50	38	23	0.16	8.86
TP-B	1.50	0	180	0.60	8.89
TP-C	3.00	56	51	0.10	7.75
TP-D	3.00	42	60	0.13	7.68
TP-E	3.50	53	93	0.06	8.42
TP-F	2.50	39	38	0.19	8.36

Operator	Checked	Approved
LJ	JWJM	WGS

# APPENDIX E PHOTOGRAPHIC RECORD

Photographic Plates- Stage 1	6 x A4
Photographic Plates- Stage 2	8 x A4





Plate 1—TP-A



Plate 2—TP-A





Plate 3—TP-B



Plate 4—TP-B





Plate 5—TP-C



Plate 6—TP-C





Plate 7—TP-D



Plate 8—TP-D





Plate 9—TP-E



Plate 10—TP-E





Plate 11—TP-F



Plate 12—TP-F





**Trial Pit TP-S01** 



Trial Pit TP-S01





**Trial Pit TP-S01** 



Trial Pit TP-S01





**Trial Pit TP-S02** 



Trial Pit TP-S02





**Trial Pit TP-S02** 





**Trial Pit TP-S03** 



Trial Pit TP-S03





**Trial Pit TP-S03** 



Trial Pit TP-S03





**Trial Pit TP-S04** 



**Trial Pit TP-S04** 





**Trial Pit TP-S04** 



**Trial Pit TP-S04** 

